State Water Resources Control Board



Division of Clean Water Programs

1001 I Street • Sacramento, California 95814 • (916) 341-5871 Mailing Address: P.O. Box 944212 • Sacramento, California • 94244-2120 FAX (916) 341-5808 • Internet Address: http://www.swrcb.ca.gov



October 24, 2001

TO: Interested Parties

SURVEY FORM FOR SENSOR FIELD STUDY

We are sending this letter to you, as someone who may have expertise in the performance of the various sensors used in UST systems. We are concerned about the performance of these sensors, specifically those in tank-top sumps, tank annular spaces, and under dispenser containment. As you know, their performance is critical in detecting leaks. Therefore, we have initiated our own study to evaluate their effectiveness under actual operating conditions.

We plan to visit 200 operating UST facilities and collect data on sensor performance. However, we recognize that our field study is limited and would be incomplete without input from those who have valuable first-hand experience with these sensors. Therefore, we are requesting your assistance to complete the enclosed survey form and return it to us. This will allow us to incorporate your knowledge and experience into our study. We estimate it will take approximately 30 minutes to complete the entire survey, however we are interested in your views even if you can only complete a portion.

Please distribute the survey to anyone in your organization who routinely works with UST leak detection sensors. This includes, but is not limited to, service technicians, inspectors, installers, and environmental managers. Please return the completed surveys by **November 15, 2001** to:

Attention: Scott Bacon

State Water Resources Control Board Department of Clean Water Program

P.O. Box 944212

Sacramento, CA 94244-2120

Fax: (916) 341-5808

If you prefer, you may complete and submit the survey online at:

http://www.calcupa.net/support/index.htm

If you have any questions regarding this survey, please contact Scott Bacon at (916) 341-5873 or email: bacons@cwp.swrcb.ca.gov.

Sincerely,

- ORIGINAL SIGNED BY -

Shahla Dargahi Farahnak, P.E., Chief Engineering Unit 2 Underground Storage Tank Program

Enclosure

UST SENSOR STUDY SURVEY

STATE WATER RESOURCES CONTROL BOARD

(Please answer all the questions that are applicable based on your experience in the field)

Information provided by: – (Leave blank if you prefer to submit this survey anonymously) Name: Company/Agency: Address: Telephone: **GENERAL INFORMATION 1.** What is your affiliation? ☐ Local Agency Inspector ☐ Technician ☐ Consultant ☐ Owner/Operator \Box Other (*Specify*) 2. How many years of experience do you have in the UST field? **3.** Average number of UST facilities you inspect/service monthly? □ Not applicable OVERALL SENSOR INFORMATION 4. Do you perform/require a functional test (i.e. accessing the sensors and activating an alarm by flipping them over, immersing them in liquid, etc.) of all sensors during the annual UST monitoring equipment certification? \square Yes \square No 5. What percentage of the sensors you encounter in the field are failing the functional tests? \Box < 5% □ 5-10% □ 10-20% □ 20**-**30% □ 30-40% □ 40**-**50% □ >50% **6.** What percentage of the sensor failures are due to the following factors: a) Poor design: $\square < 5\%$ □ 5-10% □ 10-20% □ 30-40% □ 20**-**30% □ 40-50% □ >50% b) Installation: \Box <5% □ 5-10% □ 10-20% □ 20**-**30% □ 30-40% □ 40**-**50% □ >50% □ 5-10% □ 10-20% c) Maintenance: □ <5% $\Box 20-30\%$ □ 30-40% $\Box > 50\%$ $\Box 40-50\%$ d) Programming: □ <5% □ 30-40% □ 5-10% □ 10-20% □ 20-30% □ 40-50% □ >50% e) Tampering: $\square < 5\%$ □ >50% □ 5-10% □ 10-20% □ 20-30% □ 30-40% □ 40**-**50% f) Other: $\Box 5-10\% \quad \Box 10-20\%$ □ <5% □ 20-30% □ 30-40% □ 40**-**50% □ >50% 7. Sensor failure is most common in: ☐ Steel Tanks ☐ Dry Interstice Fiberglass Tank ☐ Wet Interstice Fiberglass Tank ☐ Tank-Top (pump/fill) Sumps ☐ Under Dispenser Containment ☐ Location is not a factor in sensor failure

Appendix V, Survey Page 1 of 3

SENSOR COMPARISON

8. Please complete this section to the best of your knowledge:

	Float switch	Polymer strip	Optical 1	Prism U	Itrasonic	Conductivit	ty Capacitance change
% failure rate							
Indicate most common reason(s) for failure							
*Failure Reasons:		ogramming Poor Design		faintenanc = Please ir		Installation	T = Tampering
9. What specific	make(s) and	/or model(s)) of sensor ar	e most reli	able?		
10. What specific	make(s) and	/or model(s)) of sensor ar	e least reli	able?		
DISCRIMINA	TING SENS	SORS					
11. What percent	age of the ser	nsors you us	e/inspect/serv	vice are dis	scriminatir	ng sensors?	
Tank InterstTurbine SunUnder Dispe	nps: □ <5%	□ 5-10%	□ 10-20%	□ 20-30%	□ 30-4	0% □ 40-	
12. Based on you discriminating	r experience, g sensors?	discriminat	ing sensors a	re		_ when comp	pared to non-
☐ More reliable ☐ Less reliable ☐ Equally reliable							
13. For discrimin	ating sensors	using polyn	ner strip, wha	at is the typ	oical time	for each of th	e following?
a) <u>response in</u> □ <30sec □			□ 3-5min	□ 5-10m	in 🗆 🗆	10-20min	□ >20min
b) <u>recovery ir</u> □ <1min □			□ 5-10min	□ 10-20r	nin 🗆 🗆	>20min	□ Not reusable
c) response in $\square < 30 \text{sec}$		□ 1-3min	□ 3-5min	□ 5-10m	in 🗆 🗀	10-20min	□ >20min
d) <u>recovery ir</u> □ <1 min □		□ 5-15min	□ 15-30min	□ 30-60r	nin 🗆 🗆	>60min	☐ Not reusable

Appendix V, Survey


14. Is there a change in response times for polymer strip sensors after repeated exposure to fuel?							
 □ Response time for polymer-strip sensors increases after repeated exposure to hydrocarbons. □ Response time for polymer-strip sensors decreases after repeated exposure to hydrocarbons. □ Response time for polymer strip sensors does not change after repeated exposure to hydrocarbons. 							
15. Which of the following methods do you most often use/require when testing discriminating sensors?							
☐ Test in water only ☐ Test in product only ☐ Test in both product and water ☐ I do not test/require testing of discriminating sensors							
PUMP SHUT-DOWN FEATURE							
16. What is the typical time delay between sensor activation and pump shut-down?							
□ <5sec □ 5-10sec □ 10-30sec □ 30-45sec □ 45-60sec □ 1-2min □ >2min							
17. For sensors programmed for pump shut-down, what percent of them shut down the pump?							
□ <5% □ 5-10% □ 10-20% □ 20-30% □ 30-40% □ 40-50% □ >50							
18. What are the most common reason(s) for failure of the pump shut-down?							
 □ Programming □ Relay box (Equipment problems) □ Other (Specify) □ Tampering □ Other (Specify) 							
ADDITIONAL INFORMATION							
19. What changes can be made to improve sensor reliability?							
<u> </u>							
20. Do you have any other comments you would like to share with us?							

Appendix V, Survey

SWRCB Sensor Field Evaluation, Survey Results

71 local agency inspectors and service technicians responded to the survey. The following tables summarize their responses to a variety of questions on UST leak detection sensors.

ABOUT THE RESPONDENTS




Appendix V, Survey Results


Page 1 of 6

GENERAL SENSOR INFORMATION

Do you Require Functional Test of Sensors?


Percentage of Sensors Failing Functional Test






What Percentage of Sensor Failures are Due to Poor Design?

What Percentage of Sensor Failures are Due to Poor Installation?






Appendix V, Survey Results


Page 2 of 6






What Percentage of Sensor Failures are Due to Improper Programming?






What Percentage of Sensor Failures are Due to Tampering?

Location Where Sensor Failure is Most Common







Appendix V, Survey Results Page 3 of 6

DISCRIMINATING SENSOR INFORMATION

Percentage of Discriminating Sensors in Tank Interstice


Percentage of Discriminating Sensors in Turbine Sumps






Percentage of Discriminating Sensors in UDC

Reliability of Discriminating Sensors as Compared to Non-Discriminating







Appendix V, Survey Results

Page 4 of 6

Discriminating Sensor Response Time in Unleaded Fuel


Discriminating Sensor Recovery Time in Unleaded Fuel






Discriminating Sensor Response Time in Diesel Fuel

Discriminating Sensor Recovery Time in Diesel Fuel







Appendix V, Survey Results

Page 5 of 6

Changes in Response Time for Polymer Strips After Repeated Exposure to Fuel

How are Discriminating Sensor Being Tested?







PUMP SHUT-DOWN INFORMATION

Pump Shut-Down Delay Time

Reason for Failure of Pump Shutdown





Appendix V, Survey Results

Page 6 of 6

Online Survey Comments and Recommendations for the Sensor Field Evaluation of Underground Storage Tanks:

This is a compilation of comments and recommendations we received from our survey participants. These comments represent the views of the participants surveyed and may not reflect the opinions of the SWRCB.

- Discriminating sensors must be able to be tested in the actual product and must clear within a few minutes
- Improve maintenance of sensors and replace outdated ones.
- The polymer strip type sensor appears to be a poor design for immediate identification of a leak. Remove this type from the approval list.
- Do not allow the use of sensors associated with the MSA Tankguard. I'm not sure, but I believe that they are polymer strip discriminating sensors. They have an extremely low response and recovery time of about 15-20 minutes. Also the sensitivity of the MSA Tankguard can be adjusted and always seems to need to be adjusted at each inspection. The alarm may not sound when the sensor is being tested in liquid, but then sound when it is not being tested. I do not trust the reliability of these sensors.
- Operator training, proper maintenance and tamper proofing.
- Eliminate discriminating sensors altogether in annular spaces. Heck, eliminate them everywhere. They are only good for sumps and containment areas that are so poorly constructed that liquid intrusion is a constant problem. Repairing the sumps would be a better solution to liquid intrusion problems.
- The positive shut down sump sensors are plastic and they stick open. Some type of new stick product is needed.
- You might want to require that all sensors be replaced regularly every 2-3 years.
- Eliminate discriminating sensors unless they have <5sec-response time. They need to be designed so that corrosion and sticking do not occur. Needs to be such that maintenance is minimized since this is only done annually.
- Require quarterly maintenance and inspection of sensors.
- Make them simple and easy to place. The Tri-State feature is best on systems that have no maintenance crew.
- Overall experience with discriminating sensors is minimal, but due to survey set cases/problems, we do not allow or will approve them for use in the city. Result is problematic.
- Better design, stronger materials, and no resistors at sensor end.
- Improve design on brands listed in question 10. Discriminating sensors are not practical. I do not test them due to recovery time. Sometimes they do not recover.
- I don't know if it is possible, but what if they made a sensor that was non-stick so that sludge would not hold the float, making it stuck. The contact points would also need to be sludge proof.
- Better installation practices. Sensors are not being hung at the correct location, i.e. at the bottom of the tank or sump.

- Eliminate discriminating sensors or improve technology. Operate and test sensors under various simulated conditions. Improve technology of annular float sensors in FG tanks to improve accessibility/visual inspection/simulated testing.
- Be there at the annual maintenance checks. You learn a lot, see a lot of the important violations and disrupt the business only once. The entire focus of my inspections is the leak detection systems for piping and tanks. They must work. Operators do not like to do leak detection manually. Pushing toward all electronic monitoring is essential for the future. Get the operators out of it. Have the ATG print out the monthly .2 gph-passing test for tanks at least once a month automatically. Then the operator saves this record for the inspection.
- Testers hate to test the discriminating sensors with product because they know they will have problems getting them cleared, if at all. If the sensors won't clear, then it must be replaced, and tested. On one occasion, the technician did not have a discriminating sensor replacement with him so he had to call his shop and have someone drive one out to the site. This kept that product offline for several hours. The facility operator was not happy.
- Get rid of sacrificial sensors, and require secondary containment for all piping!!!
- My primary objective in completing this survey is to expose the problems that I have encountered in
 trying to test the sensors for the MSA Tankguard system. All other sensors that I have encountered are
 sufficiently reliable.
- The compatibility of simple contact switch sensors with the control panels is not a major issue or an operational problem. The use of discriminating sensors is a major issue even when these sensors are used with a compatible control panel.
- We hardly see discriminating sensors. The alarm needs to go through a central alarm system in which case we will know of any release. Tampering defeats the purpose of monitoring. We find improper positioning of the probe/ raised probe 80 % of the sites. Water intrusion a real problem.
- A tank system that is properly constructed and maintained should never have liquid intrusion problems and therefore there is no need for discriminating sensors.
- Owners need a good, simple manual on the tank system components, requirements, and
 responsibilities: like "straight talk on tanks" in more detail. So many stations change hands and so
 many employees are dueless, that comprehensive explanation of UST's is desperately needed to start to
 get an unformed constituency.
- Bravo box float mechanisms for dispenser containment monitoring were not mentioned in this survey but have about a 50% failure rate due to debris or loose chains. SFSFD water tests all float monitored dispenser pans.
- Sensor reliability or rather the lack there of, has caused local agencies to all other leak detection and testing requirements to UST's. The confidence level in the sensors functioning properly at any given time is low, Because of this the confidence in our UST programs goal of preventing and detecting releases is also somewhat low. Why spend a lot of time and resources when the devices are unreliable? Also, this didn't address mechanical systems. The Bravo Float system has chronic problems with not functioning properly after more than a year. The float does not leave very much room for sidewalls of channels so dirt freezes the movement. Tampering by loosening chains is extremely common. We dislike this design.
- Phasing out existing monitoring systems. I.e. pollulert, petrometer, leak-x, petrovend, etc. Notion current LG-113 should be an eventually to start planning for now.

- Discriminating sensors add approximately 10 min. per sensor for testing and returning to operability. That adds about 2 hours to a standard gas station monitoring certification inspection.
- Question 13(d)- recovery time for diesel fuel is greater than 60 minutes.
- Please remove discriminating sensors from approved method. They are not reliable and/or do not sense
 for reasonable system monitoring (if located in sump bottom with water in sump a full leak will not be
 detected if the water level is above the sensor). Question 7-Sensor failure is most common in Tank Top
 (pump/fill) Sumps and Under Dispenser Containment.
- This survey should allow free-text answers. Some pick-list choices are inadequate. At the very least, there should be a "unknown" response.
- In the past when we arrived on site for an inspection, the maintenance contractor or operator may have already tested and replaced any faulty sensors. This will skew the data you collect from inspectors, indicating higher performance rates.
- People raising probes due to surface water infiltration via rain or steam cleaning the parking lot, which violates many laws.
- Alternate technologies should be available for positive shutdown, which do not rely on the relay boxes.